Grand Staircase-Escalante National Monument Road Report

Friday, September 6, 2024

All road conditions can change RAPIDLY due to weather.

Please contact the nearest <u>GSENM Visitor Center</u>
or visit <u>Monument Travel Advisories</u> for updated conditions.

Roads to the East

Name	Date	Road	Comments
Burr Trail	8/25/2024	2WD, Impassable	Pavement is dry, then wash crossing at Halls creek is impassable, quicksand
Notom-Bullfrog	8/30/2024	2WD High Clearance	2WD High Clearance! Per Capitol Reef NPS report.
Road to Bullfrog Marina	8/30/2024	2WD High Clearance	Conditions unknown! Per Capitol Reef NPS report.
Wolverine Loop	7/9/2024	2WD High Clearance	Dry and dusty rough in places.
Cedar Wash	8/1/2024	2WD High Clearance	Road has some sandy spots.
Hole in the Rock	8/24/2024	2WD High Clearance, 4WD	Mud, standing water, road damage at 20 Mile crossing. Recommend HC-4WD for last 7 miles.
Spencer Flat	8/31/2024	2WD, 2WD High	Dry with a few areas of washboards.

Roads to the North

Name	Date	Road	Comments
Hells Backbone	8/28/2024	2WD	Washboarded!
Posey Lake to Loa	8/2/2024	2WD High Clearance	Areas of washboarding!
Whites Flat (FR #152)	8/2/2024	2WD High Clearance	Segments of washboards.
Griffin Top	8/2/2024	2WD High Clearance	Segments of washboards.
North Creek (FR #149)	8/3/2024	2WD High Clearance	Segments of washboards!
Main Canyon	8/2/2024	2WD	Dry and dusty, segments of washboards.

Roads to the Central Areas

Name	Date	Road	Comments
Smoky Mountain - Alvey Wash	8/30/2024	4WD High Clearance	Rough at Wahweap Wash. Road wet in a few spots to Smokey Hollow/Kelly grade and dry to Head of the Creeks. Conditions unknown beyond.
Left Hand Collet	8/2/2024	4WD High Clearance	Recommend HC 4WD!
Croton	8/3/2024	Impassable	Impassable due to deep mud 1.5 miles east of Alstrom Pt. Junction.
Smoky Hollow	7/21/2024	4WD High Clearance	Rough. High clearance and experience needed.

Roads to the West

Name	Date	Road	Comments
Cottonwood	9/4/2024	2WD High Clearance	Dried ruts and eroded washes make high clearance desirable.
Skutumpah	8/27/2024	2WD High Clearance	Passable with 2WD High Clearance to Johnson Canyon.
Glendale Bench	7/5/2024	2WD	Dry, dusty, areas of washboarding.
Paria Movie Set	8/19/2024	4WD High Clearance	Likely slippery south of restroom. Muddy north of there.
House Rock Valley	8/19/2024	4WD High Clearance	Rough, muddy and rutted in spots. Buckskin crossing and bypass have calf-deep water.
White House	7/5/2024	2WD	2WD conditions. Road is in good shape!